

Watermill Center



Michielli + Wyetzner Architects

Performing Arts Center, Watermill, NY

2005



Michielli and Wyetzner Architects took over the design and construction of Robert Wilson's Watermill Center in Eastern Long Island in 2004. The building required a complete gutting of the exterior facade, including all cladding, wallboard, windows, and the replacement of window wall systems, which were damaged due to lack of tolerance between the steel structural frame and the glazing system.

A zinc sinewave cladding, set against deep recessed black painted windows, was chosen for the facades, with an eifs base. An aluminum glazing system was designed to infill the steel frame.